

NEBRASKA DEPARTMENT OF ENVIRONMENTAL QUALITY Air Quality Division

REC'D

INITIAL NOTIFICATION FORM

AUG 2 0 2010

City Chappell, NE 69129 Zip 69129

Plant Address (if different than owner/operator's mailing address):

Street PO Box 487

City Chappell, NE

Zip <u>69129</u>

Plant Phone Number <u>30</u>8-874-2401

Plant Contact/Title <u>mike Oraham</u> / utility supervisor

This form must be completed, signed and submitted to the following agencies:

NDEQ Air Quality Division 1200 'N' St. Atrium, Suite 400 Lincoln, NE 68509-8922 and

Region VII EPA - Air & Waste Management

901 N. 5th Street

Kansas City, KS 66101-2907

If your facility is located in Omaha or Lancaster County, you must submit a notification to the appropriate air pollution control agency in that area and Region VII EPA.

Provide the following information for the applicable stationary engine(s). Add additional tables or rows as needed.

Unit#	Engine Startup Date	Site Rating Brake Horsepower	Displacement (liters/cylinder)	Fuel(s) Combusted	Compression Ignition	Spark Ignition	Emergency	Limited Use
1	3-15-10	1582	4.3	Diesel ULS D	₽ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	☐ YES	YES
2	0d.1941				☐ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	□ YES	☐ YES
					☐ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	☐ YES	☐ YES

Unit#	Engine Startup Date	Site Rating Brake Horsepower	Displacement (liters/cylinder)	Fuel(s) Combusted	Compression Ignition	Spark Ignition	Emergency	Limited Use
					☐ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	☐ YES	☐ YES
					☐ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	☐ YES	☐ YES
					☐ YES	4-Stroke 2-Stroke Lean Burn Rich Burn	☐ YES	☐ YES
Factor Fa	cility is a recility is an *Note: A recility is an *Note: A recility determination of the source of F ource ource of F ource ource of F ource ource of F ource ource our	najor source of area source of major source is tons per year of tion is based on new/reconstruction is \[\begin{array}{c} \text{Yes} & \text{Equiv} & \text{Price} & \text{Yes} & \text{Equiv} & \text{Price} & \text{Yes} & \text{Equiv} & Equ	a facility that ha of all HAPs comb all HAP emission ucted emergenc	pollutants (HA as a potential to bined. All other son points inside to you or limited use additional required	emit greater the sources are are the facility fender engine and the suirements un	ea sources. The ce line. > 500 horsepo der Subpart 2	e major/area sower located	at a u must
Source Ne Ext	Compress Type - C w Source* isting sour	heck the box	Ingines or Subp	art JJJJ for Sp	ark İgnition E	Engines .		
Print o	r type the	name and title	of the Responsi	ble Official for	the facility:			
Name:	<u>Mi</u> Ke	Orahan	7	Title:	Utility	Supervi	sor	
	The prAn owA planA govA rank	oner of the plant at engineer or st ernment official sting military of	resident, secretary t; upervisor of the p l, if the plant is of ficer, if the plant	y, or treasurer of plant; bwned by the Fed is located at a m	f the company deral, State, Ci nilitary base.	that owns the p	olant; government; o	
		AT INFORM OF MY KNO	IATION CONDESSED	TAINED IN T	HIS REPOR	RT IS ACCU	RATE AND	TRUE
(Signatur	MIG. (Frangen Sible Official)	7 80.			8-17 (Date)	-/0	